ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	6	Thanisandra
Street ID	**Street Name**	**Significant Landmark**
W0016	NA	R K Hegadenagra
Segment No.	**Total Length (m)**	
6/S-W0016/S044947	55.04	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	55.04	77.627897	13.070457	77.627403	13.070571	Main Road	End

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Maintenance of UGD Line in ward No. 06	750000	2020-21
Year	**Type of Work**	**Other Work Type**
2020 - 2021		
Tender	**Work Details**	**Job No. / Work Code**
Tender	UGD Line	006-20-000201
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/34/2021-22	04/02/2022	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
04/02/2022	03/02/2023	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
P Hemanth		0.00
Phone No.	**E-Mail ID**	
9448081837		

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಧಿಯಂತರು
ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-24

Scanned by CamScanner

Field Inspection Details

Number of Trees	Any Other Information	Name
0		suresh devatraj
Date of Inspection	**Remarks**	
06/05/2022		

Category	Image	Photo Remark
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	S.P.Ranganath	07/05/2022	05/06/2022	As proposed
SE	G R Devendra Nayak	07/05/2022	05/06/2022	Forwarded
EE	H T MOHANDAS	07/05/2022	05/06/2022	VERIFIED
AEE	B S Sridhar	06/05/2022	05/06/2022	Approvel
AE	Suresh Devatraj	06/05/2022	05/06/2022	Mob Verification Done
AE	Suresh Devatraj	06/05/2022	05/06/2022	For MOb Verification

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W0016

Date: 07/05/2022 **Time:** 15:41:07 RFI20220507154107

Scanned by CamScanner